TO FIT SIZE CHART

*Measurements refer to body size, not garment dimensions



R311X - TECHNICAL SHORTS

25.02.2016

	XS	S	М	L	XL	2XL	3XL
Waist in inches*	30	32	34	36	38	40	42
Waist in cm*	76	81	86	91	97	102	107
German clothing size (men)	46	48	50	52	54	56	58

HOW TO MEASURE CHEST: Place the tape measure across the back, underneath the arms and then across the fullest part of the chest.

1 Inch = 2,54 cm